



State of Ohio Environmen



Northeast District Office

* 0 H 8 5 0 0 6 1 2 2 2 6 2 0 0 7 N O V *

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

February 26, 2007

RE: WAYNE COUNTY
VILLAGE OF DOYLESTOWN PWS
COMMUNITY WATER SYSTEM
PWS ID # 8500612
STU ID # 8559594

Mr. Dennis White
Village of Doylestown
24 S. Portage St.
Doylestown, Ohio 44230

SUBJECT: Notice of Violation of the Secondary Contaminant Standards

Dear Mr. White:

On February 13, 2007, this office received the January 2007 Monthly Operating Report (MOR form 5002) from the Village of Doylestown. The MOR is provided as a means to relay compliance information about the operation of the water treatment plant. Operational monitoring is conducted throughout the month to test the treatment effectiveness of the water plant. Since Doylestown treats its water by potassium permanganate injection for manganese green sand filtration (iron and manganese removal), chlorine injection (disinfection), and phosphate addition, you are required to conduct monitoring for iron, manganese, chlorine residual, and phosphate.

Please note the following violations:

At least one sample each week for iron and manganese is required to be analyzed by a certified laboratory. In accordance with Ohio Administrative Code (OAC) 3745-82-02, plant tap iron levels must remain at or below the secondary maximum contaminant level (MCL) of 0.3 milligram per liter (mg/L) at all times. Plant tap manganese levels must remain at or below the secondary MCL of 0.05 mg/L at all times.


On the January 2007 MOR, the iron and manganese levels were reported as summarized in the following table:

Sample Collection Date	Iron Results in mg/L	Manganese Results in mg/L
January 3, 2007	0.464	0.204
January 10, 2007	0.429	0.209
January 17, 2007	0.511	0.269
January 24, 2007	0.589	0.138
January 31, 2007	0.524	0.127

These most recent iron and manganese levels may indicate that the equipment is not operating effectively and should be adjusted immediately.

If you have any questions regarding this correspondence, or if you need any assistance, please contact me at (330) 963-1194, or at my e-mail address, beth.madis@epa.state.oh.us.

Sincerely,



Beth R. Madis
Environmental Specialist
Division of Drinking and Ground Waters

BRM/ams

cc: Wayne County Health Department
Dave Evans, Ohio EPA, Central Office, DDAGW