



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

September 5, 2013

Mr. Frank Simcic
EH&S Manager
Hukill Environmental Services
7013 Krick Road
Bedford, OH 44146

RE: Hukill Environmental Services, OHD001926740/02-18-0315, Cuyahoga County, Return to Compliance

Dear Mr. Simcic:

On August 23, 2013, I met with you and Brent Forman at Hukill Environmental Services. The purpose of my visit was to inspect and photograph the four (4) hazardous waste tank dikes whose concrete coating project had been completed. The concrete containment dikes had been re-coated due to the varying degrees of disrepair the old coating was exhibiting. Minor repairs were made, if needed, prior to surface preparation and application of the new coating system.

On August 29, 2013, I received the Tank Farm Coating Project Summary document. I have reviewed the document and found it to be acceptable.

Based on my site visit and review of the Tank Farm Coating Project Summary, Hukill Environmental Services is returned to compliance with the following violations noted during my April 10 and 17, 2013, compliance evaluation inspection:

2 & 3. OAC 3745-55-93(E)(1)(c)&(f)-Tank external liner systems.


External liner systems must be free of cracks and gaps (OAC 3745-55-93(E)(1)(f)) and provided with an impermeable interior coating or lining that is compatible with the stored waste and that will prevent migration of wastes into the concrete (OAC 3745-55-93(E)(1)(c)).

No further action is required by Hukill Environmental Services regarding these violations.

MR. FRANK SIMCIC
SEPTEMBER 5, 2013
PAGE 2

Should you have any questions, please feel free to call me at (330) 963-1162 or e-mail me at marlene.kinney@epa.ohio.gov.

Sincerely,

A handwritten signature in cursive script that reads "Marlene M. Kinney".

Marlene M. Kinney
Environmental Specialist
Division of Materials and Waste Management

MMK:bo

ec Jeff Mayhugh, DMWM, CO
 Nyal McKenna, DMWM, NEDO
 Natalie Oryshkewych, DMWM, NEDO