



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

January 31, 2012

Tim Duckwall
Calgon Carbon Corporation
P.O. Box 717
400 Calgon Cardon Dr.
Pittsburgh, PA 15230

**Re: Storm Water Inspection at Barnesby Sutcliffe-A Calgon Carbon Co.
Franklin County
Permit Number: 4GR00220*DG**

Dear Mr. Duckwall:

This letter is written in follow up to an industrial storm water inspection I conducted at Barnesby Sutcliffe-A Calgon Carbon Co. located at 835 North Cassady Avenue in Columbus, Ohio on January 20, 2011. The inspection was prompted an unauthorized release of scrubber water in the approximate amount of 25 gallons, directly into separate storm sewer system within the watershed of Alum Creek.

I understand this release resulted from truck with a high load impacting a scrubber line. I am in receipt of your written detailed account of the release and have noted improvements with respect to contingencies to minimize the amount of release. I concur with your corrective measure to install a plant wide maximum height restrictor bar and recommend the bar is installed within 21 days from receipt of this letter.

If you have any questions regarding this letter, please do not hesitate to call me at our Central District Office at (614) 728-3844. In addition, please provide a response to this letter within seven days of receipt.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Brett Smith, City of Columbus, Division of Sewerage and Drainage

HK/nsm Calgon Carbon Co 1-20-2012