



**Environmental
Protection Agency**

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

January 23, 2012

William Miller
4288 Mounts Road
Alexandria, OH 43001

**Re: Construction Storm Water Inspection at 4288 Mounts Road / Licking County
Permit Number: 4GC03482*AG**

Dear Mr. Miller:

This letter is written regarding a storm water inspection I conducted at 4288 Mounts Road, Alexandria, Ohio 43001 on January 5, 2012. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Please continue to monitor vegetation to ensure a successful vegetation cover to control erosion, measured by a minimum vegetation density of 70 percent. The vegetative density has NOT been reached. In addition, more attention should be addressed for all fill slopes, specifically inside the impoundment.
- Please provide to my attention design information associated with the permanent discharge structure associated with the impoundment.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm 4288 Mounts Road 1-5-2012