



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

January 23, 2012

Donald Roberts  
State Street Realty Partners LLC  
273 Barrington Drive  
Westerville, OH 43082

**Re: Construction Storm Water Inspection at Worthington Crossing / Franklin County  
Permit Number: 4GC03212\*AG**

Dear Mr. Roberts:

This letter is written regarding a storm water inspection I conducted at Worthington Crossing located at 8080 Worthington Galena Road in Worthington, Ohio on January 5, 2012. The Agency understands these construction activities are currently covered under the General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water Permit, the following items must be addressed:

**Sediment Basins:**

- The sediment basins are receiving drainage as intended and functioning to minimize sediment laden discharges to the tributary of Alum Creek. Please maintain all basins to ensure the intended functions throughout all earth disturbing activities.
- The site has been stabilized. Please continue to monitor vegetation to ensure a successful vegetative stand measures by a minimum density of 70 percent.

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO

HK/nsm Worthingto Crossing 10-25-2011