



**Environmental  
Protection Agency**

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

Re: Hardin County  
Village of Mt. Victory  
NPDES Permit

April 13, 2012

Mr. Dan Stuck  
Village of Mt. Victory  
124 South Washington Street  
P.O. Box 7  
Mt. Victory, Ohio 43340

Dear Mr. Stuck:

On April 5, 2012, a National Pollutant Discharge Elimination System (NPDES) permit compliance inspection was conducted at the Village of Mt. Victory wastewater treatment plant. You were present and provided information regarding operation and maintenance of the plant.

During our visit, the contents of the primary lagoon cell were dark green in color and had a sulfur odor. The contents of the secondary cell were green in color. The color of the tertiary cell was clear. The discharge to Panther Creek was clear with no noticeable odor.

The dikes around the lagoons appeared to be well maintained and free of weed growth. It was noted that a sign has not been installed at the final outfall. The sign requirement can be found in Part II, Item Q. of the NPDES permit.

A review of the discharge monitoring reports from June 2011 to March 2012 shows that there has been one effluent limit violation for pH in September 2011. The specific instance of non-compliance is enclosed on a separate sheet.

If you have any questions, please contact me at 419-373-3053.

Sincerely,

Ryan Gierhart  
Division of Surface Water

/jlm

Enclosure

pc: Ms. Ann Scott, Industrial Fluid Management  
Mayor and Council  
ec: Inspection Tracking

Get New Data									
Permit No.	Reporting Period	Station	Reporting Code	Parameter	Limit Type	Limit	Reported Value	Violation Date	
2PA00046*DD	September 2011	001	00400	pH	1D Conc	9.0	9.32	9/14/2011	