



**Environmental  
Protection Agency**

**John R. Kasich, Governor**  
**Mary Taylor, Lt. Governor**  
**Scott J. Nally, Director**

Re: Huron County  
Huron Valley Trailer Park  
NPDES Permit 2PY00077\*AD  
**Notice of Violation (NOV)**

**CERTIFIED MAIL 7009 1410 0001 1842 5566**

April 13, 2012

Mr. Arthur and Mrs. Judith Frank, Owners  
Huron Valley Trailer Park  
3066 South Prior Road  
Akron, Ohio 44319

Dear Mr. and Mrs. Frank:

On February 15, 2012, I conducted a brief inspection of the wastewater treatment facilities serving the Huron Valley Trailer Park. At the time of my inspection, the plant was operating. No samples were taken to verify proper operation. Our observations and recommendations are as follows:

1. The contents of the aeration tanks were a light grey color with light foam. The aeration rate was very weak. The sound of leaking air was detected coming from the blower unit. These problems should be investigated and corrected to ensure that the aeration tank receives an adequate amount of air to treat the wastewater.
2. The water in the clarifier was murky and grey in color and there was solids buildup in the outlet weir. There was a significant amount of sludge floating on the surface of the clarifier. Effluent from the clarifier was murky with light solids.
3. The overall condition of the plant remains "poor". Concrete is still breaking off the tanks and the metal grating is rusty and in poor condition. The facility is in violation of the compliance schedule contained in Part I, C of the NPDES permit, which requires repairs and plant upgrades to be constructed. We strongly recommend that the concrete deterioration and grating be addressed immediately to reduce the safety hazard that currently exists (see enclosed photos).
4. There were no records or log book available at the plant in order to verify compliance with the Operator of Record and minimum staffing requirements of Part II, Items A & B of your NPDES permit and Ohio Administrative Code (OAC) 3745-7.

Mr. and Mrs. Frank  
April 13, 2012  
Page Two

5. Ohio EPA has not received the Discharge Monitoring Reports (DMR) from Huron Valley Mobile Home Park since the NPDES permit became effective in March, 2009. Submission of the DMR data is a requirement of your NPDES permit (Part III, Item 4, Reporting).

Overall, the facility remains in significant non-compliance with the monitoring requirements and schedule of compliance contained in its NPDES permit.

Please inform this office in writing, within 10 days, as to the reasons for the above referenced violations, as well as a description of the actions taken or proposed to prevent further violations. Your response should include the dates, either actual or proposed, for completion of the actions.

If you have any questions regarding this letter, please contact me at (419) 373-3003 or via email at [andrew.gall@epa.state.oh.us](mailto:andrew.gall@epa.state.oh.us)

Sincerely,



Andrew Y. Gall  
Division of Surface Water

/jlm

Enclosure: Inspection Photos

pc: Janean R. Weber, Assistant Attorney General, Ohio Attorney General's Office  
Huron County Health Department

ec: Rachel DeMuth, OEPA-CO-DSW  
Michael Shapiro, OEPA-CO-Legal  
Inspection Tracking



**Huron Valley MHP Wastewater Treatment Plant**

February 15, 2012

Photo By: Andrew Gall, Ohio EPA, NWDO-DSW

Aeration Tank



**Huron Valley MHP Wastewater Treatment Plant**

February 15, 2012

Photo By: Andrew Gall, Ohio EPA, NWDO-DSW

Clarifier