



**Environmental
Protection Agency**

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

May 10, 2012

Al Coughlin
Coughlin Automotive
9000 Broad Street SW
Pataskala, Ohio 43062

**Re: Construction Storm Water Inspection at Pataskala Town Center / Licking County
Permit Number: 4GC01147 *AG**

Dear Mr. Coughlin:

This letter is written regarding a storm water inspection I conducted at Coughlin Automotive located on State Route 16 in Licking County on April 12, 2012. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- The area remains idle. Please continue with your required self-inspection reports every seven days or within 24 hours of a precipitation event equal to or greater than 0.5 inches. A log of all inspections must be maintained.

Post Construction

- I understand the large centralized basin was modified for sediment control. This modification was temporary in nature. Due to the slow rate of development over the years this temporary modification has been in use for several years.
- The use of the temporary riser has resulted in a prolonged high water level. As a precaution, I strongly recommend the embankment of the pond is routinely inspected to ensure structural integrity.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Al Coughlin

HK/nsm Coughlin Automotive 8-27-2010

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov