



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

June 26, 2012

Steve Geiger  
Geiger Excavating Inc.  
65 Southwind Drive  
Gahanna, OH 43230

**Re: Notice of Violation at Bedford II Landfill Cover  
Franklin County Permit Number: 4GCO3047\*AG**

Dear Mr. Geiger:

This letter is written regarding the storm water inspection conducted by Elizabeth Pleta, Alicia Rector, Katie Rumora, and Brittany Turner of the Ohio EPA at Bedford Landfill II on June 19, 2012. The Agency understands these construction activities are currently covered under the General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water Permit, the following items must be addressed:

**Sediment and Erosion Controls:**

- The skimmer on centralized basin has become dislodged from outlet structure resulting in failed sediment control for this site. This must be repaired within 48 hours of receiving this letter.
- The centralized basin has exceeded 50% of intended capacity. The basin must be cleaned out within seven days.
- The current drainage to the silt fencing on the west side of the site exceeds the designed capacity. Outlying areas are currently not directed to the centralized basin, resulting in direct violation of the general permit. An approved alternate basin or equivalent must be developed within seven days.
- No sediment controls were found on the southwest side of the site. This is a direct violation of the general permit.

Steve Geiger  
Geiger Excavating Inc.  
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us). In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow-up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

A handwritten signature in black ink, appearing to read "Harry Kallipolitis", with a long horizontal flourish extending to the right.

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office



**Figure 1 West side area exceeding silt fence capabilities**



**Figure 2 Southwest area lacking sediment controls**



**Figure 3 Southwest area lacking sediment controls**



**Figure 4 centralized sediment basin exceeding 50% capacity**