



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 5, 2012

Mike Bashore
Franklin County Engineers Office
970 Dublin Road
Columbus, OH 43215

**Re: Storm Water Inspection at Alum Creek Drive at Groveport Rd Overpass
Roundabouts Permit #: 4GC03686*AG**

Dear Mr. Bashore:

This letter is written regarding the storm water inspection conducted by Katie Rumora of the Ohio EPA at the intersection of Alum Creek Drive and Groveport Road on June 28, 2012. The Agency understands these construction activities are currently covered under the General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water Permit, the following items must be addressed:

- The silt fence on the southeast corner of the site appears to have failed and will require maintenance at this time. This must be repaired within three days of receiving this letter.

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Alum Creek Drive At Groveport Rd. Overpass and Roundabouts 6-28-2012