



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

July 12, 2012

Daimler Group  
Tucker Bohm  
1533 Lake Shore Drive  
Columbus, Ohio 43204

**Re: Storm Water Inspection at Westar V.  
Permit Number: 4GC03760\*AG**

Dear Mr. Bohm,

This letter is written in follow-up to a construction storm water inspection by Alicia Rector and Elizabeth Pleta of the Ohio EPA, at Westar V, located in Franklin County on July 03, 2012. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

**Sediment and Erosion Controls**

- Straw wattles in this setting are proving to be insufficient in meeting the minimum conditions of the General Permit. Please provide alternate sediment controls or completely seed and stabilize the slopes within seven (7) days receipt of this letter (See Figure 1).
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.
- Inlet protections are required provided the storm sewer system is not routed to an approved centralized sediment basin otherwise demonstrate an acceptable alternative (See Photo Figure 2).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

Enclosure


HK/nsm Westar V 2012

Central District Office  
50 West Town Street, Suite 700  
P.O. Box 1049  
Columbus, OH 43216-1049


614 | 728 3778  
614 | 728 3898 (fax)  
[www.epa.ohio.gov](http://www.epa.ohio.gov)



**Figure 1: Needs Protection from Erosion**



**Figure 2: Void of Dandy Bag**



**Figure 3: Straw wattle proves to be insufficient**