



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 13, 2012

Jeff Cutler
Westerville North Self Storage
591 Carle Ave
Lewis Center, OH 43035

**Re: Storm Water Inspection at Westerville North Self Storage
Permit Number: 4GC03873*AG**

Dear Mr. Cutler:

This letter is written in follow-up to a construction storm water inspection by Alicia Rector and Elizabeth Pleta of the Ohio EPA, at Westerville North Self Storage located at 6330 Frost Road, Westerville Ohio on July 03, 2012. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

Sediment and Erosion Controls

- The silt fence on the western portion of the site has failed and will require maintenance at this time (See Photo Figure 1).
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days (See Photo figure 2).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Westerville North Self Storage 7-3-2012



Figure 1: Silt fence along perimeter needs maintenance



Figure 2: Need Protection from Erosion