

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: EW/C

Visit date: 7/12/12 Permit # 16C04277AG

Site Name: former Hexion Specialty Chemicals

Site Address: 630 Glendale Milford Road Woodlawn OH 45215

People contacted on site (attach business cards): No one contacted

Their phone and e-mail: _____

1. Did you see the following on site?

ITEM	Yes/No	Not requested	Comments
NOI			
Coverage letter			
SWP3			
Inspection records			
Contractor & Subs signature document			

2. Acreage disturbed (circle): < 1 acre >1 but <5 acres >5 but <10 acres 13.57 >10 acres ??

3. Site status,; Clearing/grubbing Rough grading Storm sewers in Streets in
 Utilities installed Final grade Final stabilization

4. Are BMPs needed on site? See Back for notes

5. Are BMPs on site effective? All Some None No BMPS

Explain: _____

6. What post construction controls are shown on the SWP3? N/A

7. Were photos taken and saved? Yes

8. Was an NOV issued?

Notes:

- Large Demolition project
- Lot of Equipment moving staged off site
- Photos taken
- follow up call to be made