

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: EWC Visit date: 7/24/11 Permit # IGC04027*AG

Site Name: Mt Nebo United Methodist Church

Site Address: 11693 START 774 Bethel OH 45106

People contacted on site (attach business cards): Secretary in Church Admin Bldg (see me after contacts)

Their phone and e-mail: _____

1. Did you see the following on site?

ITEM	Yes/No	Not requested	Comments
NOI			
Coverage letter			
SWP3			
Inspection records			
Contractor & Subs signature document			

2. Acreage disturbed (circle): < 1 acre 3.7 >1 but <5 acres >5 but <10 acres >10 acres ??

3. Site status: Clearing/grubbing Rough grading Storm sewers in Streets in
Utilities installed Final grade Final stabilization

4. Are BMPs needed on site? Yes

5. Are BMPs on site effective? All Some None No BMPS

Explain: Culvert in Basin needs protection until stable

Construction Ted Peters → 513-505-9028
 Burden

Pastor Mike Starkey

6. What post construction controls are shown on the SWP3? N/A

- Sewer & Basin Seen Though.

7. Were photos taken and saved? Yes

8. Was an NOV issued? No

Notes:

- ask for SWP3
- Creek Crossing?
- Paved Outlet in Basin

