



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 2, 2012

Mr. Adam Goetzman
Green Township Board of Trustees
6303 Harrison Avenue
Cincinnati, OH 45247-7818

RE: Hamilton County, 5195 North Bend Road, Reconnaissance Inspection

Dear Mr. Goetzman:

On July 20, 2012, I conducted a Reconnaissance Inspection at 5195 North Bend Road (formerly known as the Beiderman Educational Center) WWTP (NPDES Permit No. OH0112461; OEPA Permit No. 1PZ00051*BD) located in Green Township, Hamilton County, Ohio. The facility appeared to be operating normally. No violations were discovered during the inspection and, therefore, a response to this inspection report is not required.

If you have any questions or concerns regarding this matter, please feel free to contact me at (937) 285-6107 or via email at robert.ostendorf@epa.ohio.gov.

Sincerely,

Bob Ostendorf Jr.
Environmental Specialist
Division of Surface Water
Permits Section

Enclosure

BO/ca



State of Ohio Environmental Protection Agency
Southwest District Office

NPDES Compliance Inspection Report

Section A: National Data System Coding					
Permit #	NPDES#	Month/Day/Year	Inspection Type	Inspector	Facility Type
1PZ00051*BD	OH0112461	7/20/12	C	S	2

Section B: Facility Data		
Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Board of Trustees Green Township 5195 North Bend Road Cincinnati, OH	1145	October 1, 2006
	Exit Time	Permit Expiration Date
	1220	September 30, 2011
Name(s) and Title(s) of On-Site Representatives	Phone Number(s)	
Name, Address and Title of Responsible Official	Phone Number	

Section C: Areas Evaluated During Inspection					
(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)					
S	Permit	N	Flow Measurement	N	Pretreatment
S	Records/Reports	N	Laboratory	N	Compliance Schedule
S	Operations & Maintenance	N	Effluent/Receiving Waters	N	Self-Monitoring Program
N	Facility Site Review	N	Sludge Storage/Disposal	N	Other
N	Collection System				

Section D: Summary of Findings (Attach additional sheets if necessary)	
<p>No violations discovered during the inspection. The blowers were operating at the time of the inspection. The facility was not discharging at the time of the inspection.</p>	
Inspector	Reviewer
 Bob Ostendorf Jr. Environmental Specialist Division of Surface Water Southwest District Office	 Martyn Burt Compliance & Enforcement Supervisor Division of Surface Water Southwest District Office
8-3-12 Date	8/6/2012 Date