



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 14, 2012

Ms. Stephanie Simcox
Parker Hannifin Corporation
725 North Beech Street
Eaton, Ohio 45320

RE: PARKER HANNIFIN RECONNAISSANCE INSPECTION (RI)

Dear Ms. Simcox:

On August 9, 2012, I conducted an Reconnaissance Inspection at the Parker Hannifin facility in Lewisburg, Ohio. A copy of my inspection report is enclosed. The inspection report notes no deficiencies.

Based on my observations of the site's operations, it appears the facility is in substantial compliance with the terms of its Industrial Storm Water Discharge Permit.

If you have any questions or comments concerning the contents of this letter, please feel free to contact me at this office.

Sincerely,

Maureen M. Ware
Environmental Specialist
Division of Surface Water

Enclosure

ec: Preble County Health Department

MMW\bp

Industrial Storm Water Reconnaissance Inspection

Name of facility: Parker Hannifin Corporation

Address: 700 West Cumberland Street, Lewisburg, Ohio

Permit number: 1GR00685 Applicable permit sector; AA1

Date of visit: 8/9/2012 Time started: 2:00 PM Time ended: 3:00 PM

Facility representative(s): Stephanie Simcox

OEPA Inspector: Maureen Ware

SWP3

- A. Did the facility representative produce an SWP3? **Y**
- A1. Did it include a site map? **Y**
- A2. Did it include schedules and procedures for the quarterly routine facility inspections? **Y**
- A3. Did it include schedules and procedures for the comprehensive annual facility inspection? **N**
- A4. Did it include schedules and procedures for the quarterly visual assessment of storm water discharges ? **Y**
- A5. If benchmark monitoring is required, does the SWP3 describe how and when that will be done? **NA**

Comments:

Inspection records:

- B. Were inspection records available? N/A – did not ask for them.

Comments:

Site Observations:

- C. Are materials stored exposed to weather? **N**
If Yes, list materials.
- D. Are there any structural storm water management practices used onsite?
Examples include grassed swales, permeable pavement, inlet filters, detention ponds, engineered wetlands, mulch berms, silt fence, rain gardens . **Y**
- E. Number of outfalls from site/number inspected: 1
- F. Did any show evidence of pollutants discharged in the storm water? **N**
If yes, describe;
- G. Other observations/comments;