



**Environmental  
Protection Agency**

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

August 13, 2012

RE: CUYAHOGA COUNTY  
CITY OF BEACHWOOD  
EATON CORPORATE HEADQUARTERS  
CONSTRUCTION STORM WATER  
PERMIT NO: 3GC04909

**NOTICE OF VIOLATION**

Mr. David Meehan  
The Albert M. Higley Co  
2926 Chester Avenue  
Cleveland, OH 44114

Mr. Thomas Agresta Jr.  
Mr. Excavating  
8616 Euclid Chardon Road  
Kirtland, OH 44094

Dear Mr. Meehan and Mr. Agresta:

On August 9, 2012, I performed a compliance inspection for storm water best management practices (BMPs) at the above referenced site. I was accompanied by Steve Handler, Inspector with the GPD Group for the City of Beachwood. While on site, I met with Mike Pierce, Superintendent of the site with The Albert M. Higley Co. Our records indicate that The Albert M. Higley Co has obtained coverage under the Ohio EPA General Storm Water National Pollutant Discharge Elimination System (NPDES) Permit for Construction Activities #3GC04909\*AG.

After review of the site and Storm Water Pollution Prevention Plan (SWP3), I noted the following violation and deficiencies in BMP implementation:

1. **Failure to fix a sediment control deficiency that a previous inspection revealed.** This is a violation of Part III.G.2.i.i of the NPDES permit. The catch basin in the Northeast corner of the property and the two catch basins along that road need inlet protection.
2. The site should be kept free of trash and debris. Please clean up trash and dispose of it properly.
3. There was a small concrete spill on the backside of the property. Please clean up this concrete and concrete residue that has flowed into the ditch.
4. A section of the silt fence was knocked down. Please fix this and pull the dirt away from it.
5. The stabilized area next to the sidewalk on Eaton Boulevard is being washed away by any rainfall. The silt fence along the other side of this sidewalk should be extended to help with this problem.

EATON CORPORATE HEADQUARTERS  
AUGUST 13, 2012  
PAGE 2 OF 2

If you have further questions, please contact Dan Bogoevski, District Engineer of the Division of Surface Water, at (330) 963-1145 or by e-mail at [dan.bogoevski@epa.state.oh.us](mailto:dan.bogoevski@epa.state.oh.us).

Sincerely,

A handwritten signature in black ink, appearing to read 'Katie', with a long, sweeping horizontal line extending to the right.

Katie Bowman  
Assistant to the District Engineer  
Division of Surface Water

KB/cs

cc: Matt Adkins, Project Engineer, GPD Group, City of Beachwood  
Steve Handler, Inspector, GPD Group, City of Beachwood  
Mike Pierce, Superintendent, The Albert M. Higley Co  
Paul Globokar, Tenant Coordinator, Skye Group  
Todd Houser, Cuyahoga SWCD  
Merle S. Gorden, Mayor, City of Beachwood

Attachments: Photos

## INSPECTION PHOTOS

### Eaton Corporate Headquarters



**Figures 1-3:** Catch basins that need inlet protection



**Figure 4:** Trash in the backside ditch

**Figure 5:** Concrete spill with runoff that leads to a sediment trap



**Figure 6:** Section of silt fence that has been knock down



**Figure 7&8:** Area of side walk with erosion and where the silt fence needs to be extended

City of Beachwood, Cuyahoga County  
Photos taken on August 9, 2012  
Photos taken by Katie Bowman, DSW