



**Environmental
Protection Agency**

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 14, 2012

RE: CUYAHOGA COUNTY
MAYFIELD VILLAGE
MAYFIELD HIGH SCHOOL
CONSTRUCTION STORM WATER
PERMIT NO: 3GC05697

Mr. John Folkman
Mayfield City Schools
1101 SOM Center Road
Mayfield, OH 44124

NOTICE OF VIOLATION

Dear Mr. Folkman:

On August 13, 2012, I performed a compliance inspection for storm water best management practices (BMPs) at the above referenced site. I was accompanied by Tom Cappelo, Engineer with Stephen Hovancsek & Associates. While on site, we met with Gene Delzoppo, Construction Superintendent with JTO, Inc. Our records indicate that Mayfield City Schools has obtained coverage under the Ohio EPA General Storm Water National Pollutant Discharge Elimination System (NPDES) Permit for Construction Activities #3GC05697*AG.

After review of the site and Storm Water Pollution Prevention Plan (SWP3), I noted the following violations in BMP implementation:

1. **Failure to maintain or install a sediment control as noted in a previous inspection.**
This is a violation of Part III.G.2.i.i of the NPDES permit. The catch basins around the baseball field have failing inlet protection. The inlet protection is not the type specified in the SWP3. Please install proper inlet protection.
2. If areas disturbed by construction activity will not be reworked within 21 days of the last date they were disturbed, the NPDES permit requires temporary stabilization to be initiated within seven days of last disturbance. There appear to be areas of the site where temporary stabilization is appropriate.

If you have further questions, please contact Dan Bogoevski, District Engineer of the Division of Surface Water, at (330) 963-1145 or by e-mail at dan.bogoevski@epa.state.oh.us.

Sincerely,

Katie Bowman
Assistant to the District Engineer
Division of Surface Water

KB/cs

cc: Tom Cappelo, Engineer, Stephen Hovancsek & Associates
Todd Houser, Cuyahoga SWCD
Bruce G. Rinker, Mayor, Mayfield Village

Attachments: Photos

INSPECTION PHOTOS

Mayfield High School



Figures 1&2: Catch basins around baseball field



Figure 3: Area to the right of the home bleachers of the football stadium

Mayfield Village, Cuyahoga County
Photos taken on August 13, 2012
Photos taken by Katie Bowman, DSW