

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: EWC

Visit date: 8/21/12 Permit # 16C04093*AG

Site Name: Cincinnati Volunteers of America

Site Address: 7938 Hamilton Avenue Mt Healthy OH

People contacted on site (attach business cards): No one contacted on site.

Their phone and e-mail: _____

1. Did you see the following on site?

ITEM	Yes/No	Not requested	Comments
NOI			
Coverage letter			
SWP3			
Inspection records			
Contractor & Subs signature document			

2. Acreage disturbed (circle): < 1 acre 1.08 >1 but <5 acres >5 but <10 acres >10 acres ??

3. Site status,; Clearing/grubbing Rough grading Storm sewers in Streets in
 Utilities installed Final grade Final stabilization

4. Are BMPs needed on site? Site is Finished

5. Are BMPs on site effective? All Some None No BMPS

Explain: _____

6. What post construction controls are shown on the SWP3? N/A

7. Were photos taken and saved? Yes

8. Was an NOV issued? No

Notes:

- Request NOT