

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: EWC

Visit date: 8/21/12 Permit # 16C04329*AG

Site Name: Menards Site Plan 2012

Site Address: 2700 Block Cunningham Dr / Lot A-2 Euendale Commons

People contacted on site (attach business cards): No one contacted on site

Their phone and e-mail: _____

1. Did you see the following on site?

ITEM	Yes/No	Not requested	Comments
NOI			
Coverage letter			
SWP3			
Inspection records			
Contractor & Subs signature document			

2. Acreage disturbed (circle): < 1 acre >1 but <5 acres >5 but <10 acres 13.4 Acres >10 acres ??

3. Site status,; Clearing/grubbing Rough grading Storm sewers in Streets in
 Utilities installed Final grade Final stabilization

4. Are BMPs needed on site? Site not started

5. Are BMPs on site effective? All Some None No BMPS

Explain: _____

6. What post construction controls are shown on the SWP3 ? N/A

7. Were photos taken and saved? *yes*

8. Was an NOV issued? *No*

Notes:

- Find out when breaking ground.