



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 1, 2012

Jeff Baker
Makdrew Storage Condos
8230 Benadum Road
Carroll, OH 43112

Re: Makdrew Storage Condos, Ph. 1 / Fairfield County

Dear Mr. Baker:

This letter is written in follow-up to a construction storm water inspection that I conducted on July 24, 2012, at the Makdrew Storage Condos, Phase 1, located at 8230 Benadum Road. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

Sediment and Erosion Controls:

- There was no active construction at the site during the inspection. There was no erosion leaving the site and no barren areas. You are in compliance with your General Storm Water Permit.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851.

Sincerely,

Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

ec: Greg Sanders, DSW/CDO

GS/nm Makdrew Storage Condos, Ph. 1, July 24, 2012

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov