



**Environmental
Protection Agency**

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

Re: Sandusky County
Carmeuse Lime, Inc. - Millersville Plant
Industrial Wastewater

September 7, 2012

Ms. Stacey Rader
Carmeuse Lime, Inc. - Millersville Plant
1967 West County Road 42
Bettsville, Ohio 44815

Dear Ms. Rader:

On August 29, 2012, a National Pollutant Discharge Elimination System (NPDES) permit compliance inspection was conducted of Carmeuse Lime Inc. - Millersville Plant. You, Mr. Don Hardy, Production Manager of Carmeuse, Ms. Mary Beth Cohen of Ohio EPA and I were present during the inspection. At the time of the inspection, a clear effluent was observed at both outfall 001 and 005.

We have received your NPDES permit renewal application. The permit renewal is currently being drafted and will be available shortly for your review.

A review of your discharge monitoring reports has also been conducted. Several permit limit violations were noted (January 2007 – July 2012) and are enclosed.

If there are any questions, please contact Mary Beth Cohen at (419) 373-3014.

Yours truly,

Peggy B. Christie
Division of Surface Water

/jlm

Enclosures

pc: Mr. Don Hardy, Plant Production Manager

ec: Inspection Tracking



State of Ohio Environmental Protection Agency
Northwest District Office

NPDES Compliance Inspection Report

Section A: National Data System Coding

Permit #	NPDES#	Month/Day/Year	Inspection Type	Inspector	Facility Type
OH0030031	2IJ00032	Aug 29, 2012	C	S	2

Section B: Facility Data

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Carmeuse Lime, Inc. 3967 County Rd. 41 Millersville, OH 43435	9:30 AM	Aug. 1, 2007
	Exit Time	Permit Expiration Date
	10:30 AM	July 31, 2012
Name(s) and Title(s) of On-Site Representatives	Phone Number(s)	
Ms. Stacey Rader, Mr. Don Hardy, Production Manager	(419) 638-3057	
Name, Address and Title of Responsible Official	Phone Number	
Mike Klenda, Plant Manager 3964 County Rd. 41 Millersville, OH 43435	(419) 638-3057	

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

S	Permit	N	Flow Measurement	N	Pretreatment
N	Records/Reports	N	Laboratory	N	Compliance Schedule
S	Operations & Maintenance	S	Effluent/Receiving Waters	S	Self-Monitoring Program
S	Facility Site Review	N	Sludge Storage/Disposal		Other
N	Collection System				

Section D: Summary of Findings (Attach additional sheets if necessary)

[Empty box for Summary of Findings]

Inspector

Reviewer

	9/12/12		9/12/12
Peggy B. Christie Division of Surface Water Northwest District Office	Date	Thomas Poffenbarger, P.E. Water Quality Engineer II/Unit Supervisor Division of Surface Water Northwest District Office	Date

Carmeuse Lime, Inc. - Millersville Plant

NPDES Limit violation from January 2007 - July 2012

Permit No	Reporting Period	Station	Reporting Code	Parameter	Limit Type	Limit	Reported Value	Violation Date
2IJ00032*ID	February 2008	005	00530	Total Suspended Solids	30D Conc	30	68.	2/1/2008
2IJ00032*ID	February 2008	005	00530	Total Suspended Solids	1D Conc	45	68.	2/12/2008
2IJ00032*ID	June 2009	001	00530	Total Suspended Solids	30D Conc	30	40.	6/1/2009
2IJ00032*ID	June 2009	001	00530	Total Suspended Solids	30D Qty	46.6	79.9392	6/1/2009
2IJ00032*ID	June 2009	001	00530	Total Suspended Solids	1D Qty	69.9	79.9392	6/19/2009
2IJ00032*ID	June 2010	001	00530	Total Suspended Solids	30D Qty	46.6	112.414	6/1/2010
2IJ00032*ID	June 2010	001	00530	Total Suspended Solids	1D Qty	69.9	112.414	6/9/2010