

This site is right next to permit 16C04257 *AG1

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS

Visit date: 09/17/12

Permit # 16C04136 *AG1

Site Name: Miami University - Maple Street Station Dining & Residence Hall

Site Address: Maple St South of Center for Performing Arts OH 45056

People contacted on site (attach business cards): Jeff Haines

Their phone and e-mail: (513) 754-1700 jhaines@quandel-ohio.com

1. Did you see the following on site?

ITEM	Yes/No	Not requested	Comments
NOI			
Coverage letter			
SWP3	yes		
Inspection records	No		
Contractor & Subs signature document			

2. Acreage disturbed (circle): < 1 acre >1 but <5 acres >5 but <10 acres >10 acres ??

3. Site status: Clearing/grubbing Rough grading Storm sewers in Streets in
Utilities installed Final grade Final stabilization

4. Are BMPs needed on site? Gravel pad needs attention

5. Are BMPs on site effective? All Some None No BMPS

Explain: Geo-tech fiber needs cleaning over storm drain

6. What post construction controls are shown on the SWP3 ?

yes

7. Were photos taken and saved?

8. Was an NOV issued?

Notes:

yes

No