



**Environmental
Protection Agency**

Gov. **Richard** Governor
Lt. **Casey** Lt. Governor
Director

September 11, 2012

Harry Bruner
Bruner Land Company, Inc.
P.O. Box 98
Byesville, OH 43723

Re: Bruner Sullivan Development / Franklin County

Dear Mr. Bruner:

This letter is regarding the storm water inspection that I conducted on September 6, 2012, at Bruner Sullivan Development, located at 9036 Chamberlin Road, Darbydale, Ohio. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following:

Sediment and Erosion Controls:

- There was no active construction at the site during the inspection. There did not appear to be any erosion leaving the site and all barren areas were stabilized. You are in compliance with your General Storm Water Permit.
- Please be aware when construction activity begins, that the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851.

Sincerely,

Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

ec: Greg Sanders, DSW/CDO

GS/nsm Bruner Sullivan Development, September 6, 2012