



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

October 9, 2012

Christian Elliott
Ohio Soil Recycling LLC
2101 Integrity Drive S.
Columbus, OH 43209

**Re: Storm Water Inspection at Ohio Soil Recycling / Franklin County
Permit #: 4GC03436*AG**

Dear Mr. Elliott:

This letter is in follow up to two storm water inspection I conducted on September 13th, 2012 and September 19, 2012. The purpose of the inspection was to evaluate the surface impoundments to determine eligibility under an individual NPDES permit. John Owen and Phil Farnlacher with Ohio EPA were present during the inspection on September 19, 2012. During the inspection we evaluated the surface impoundments and storm water collection system associated with remediation activities at your site. The perimeter berm on the north end of the facility has been roughed in to maximize drainage from the clean fill area to the surface impoundment intended for sediment control. In addition on site grading will be conducted in such a manner to maximize drainage to the sediment impoundment area #2.

I noted a small leak from the sediment pond #1 emitting from the discharge pipe. At the time of my inspection I indicated that a bentonite seal should be administered to the riser structure once the level of the pond is down sufficient enough to address repairs.

Based on observations we are forwarding to your attention the forms necessary to complete an application for coverage under an individual NPDES permit. The application and forms can be found at the following address: <http://www.epa.ohio.gov/dsw/permits/npdesform.aspx>

If you have any questions regarding these forms please do not hesitate to contact me at our Central District Office at (614)728-3844 or via my email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/stw Ohio Soil Recycling 9-21-12