



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

November 13, 2012

Ray Baker
Woody's Auto Salvage
1988 McKinley Avenue
Columbus, OH 43204

Dear Mr. Baker:

This letter is written regarding my storm water inspections conducted at Woody's Auto Salvage located at 1988 McKinley Avenue in Columbus Ohio on November 8, 2012. I understand this facility is currently covered under the General Storm Water Permit Associated with Industrial Activities. Your facility permit number is 4GR00399*DG. The following items were noted during the inspection

Storm Water Permit:

- The General Permit for this facility has expired. The facility must seek re-authorization under the Multi Sector General Storm Water Permit. The permit, application and guidance material can be found at the following address http://www.epa.ohio.gov/dsw/permits/GP_IndustrialStormWater.aspx.
- Please submit your application for renewal within seven days from receipt of this letter.

Storm Water Pollution Prevention Plan (SWPPP)

- The SWPPP must be updated within 180 days to reflect the new conditions of the General Permit. Again, please refer to "Sector M" for the additional conditions in the link provided above for reference.

Yard Inspection:

- Based on our site observations, the majority of the yard was not stained with oil with a few minor exceptions near the transmission/engine break down area and adjacent to the front loader near the entrance. These oil stained areas must be cleaned and the soils properly disposed within seven days from receipt of this letter.

Ray Baker
Woody's Auto Salvage
Page 2 of 2

- Please provide a permanent plug for the vehicle breakdown area and ensure any release of accumulated storm water within the areas of containment is conducted in such a manner not to pose a threat to storm water quality. Release logs must be incorporated in your inspection logs for this site.
- Please provide a permanent storage area for your batteries with no exposure to storm water. I did note a temporary storage area for the batteries where exposure was noted.
- All used fluids were contained within areas of secondary containment with the exception of one receptacle which should be relocated immediately.

If you have any questions regarding this letter or my inspections, please do not hesitate to contact me at our Central District Office at (614) 728-3844. In addition, please provide a written response to this letter within in 10 days of receipt.

Sincerely,



Harry Kallipolitis
Environmental Specialist
Division of Surface Water
Central District Office

c: Scott Shields, City of Columbus