



John R. Kasich, Governor
 Mary Taylor, Lt. Governor
 Scott J. Nally, Director

December 12, 2012

Re: Ross County
 Clarksburg WWTP
 Reconnaissance Evaluation Inspection
 NPDES Permit OPA00001*GD
 Correspondence (PWW)

Ms. Sue Bethel, Mayor
 Village of Clarksburg
 P.O. Box 187
 Clarksburg, Ohio 43115

Dear Ms. Bethel:

On November 14, 2012, I conducted an inspection of the Clarksburg wastewater treatment plant (WWTP). The purpose of the inspection was to determine the facility's compliance status with the terms and conditions of NPDES permit number OPA00001*HD. A copy of the inspection report is attached.

As a part of the inspection, we have reviewed your self-monitoring reports from January 1 to November 1, 2012. Our review indicates the plant violated the NPDES permit number OPA00001*HD several times. The specific dates and reported values are listed below:

Station	Reporting Code	Parameter	Limit Type	Limit	Reported Value	Violation Date
001	00530	Total Suspended Solids	30D Qty	2.7	2.88985	1/1/2012
001	00530	Total Suspended Solids	7D Qty	4.1	4.82209	1/15/2012
001	00530	Total Suspended Solids	30D Qty	2.7	2.79409	2/1/2012
001	00530	Total Suspended Solids	30D Conc	12	13.5	3/1/2012
001	00530	Total Suspended Solids	30D Qty	2.7	2.95703	3/1/2012
001	00530	Total Suspended Solids	7D Conc	18	29.	3/15/2012
001	00530	Total Suspended Solids	7D Qty	4.1	6.5859	3/15/2012
001	00610	Nitrogen, Ammonia (NH3)	30D Conc	1.0	1.31	8/1/2012
001	00610	Nitrogen, Ammonia (NH3)	7D Conc	1.5	1.81	8/15/2012
001	00610	Nitrogen, Ammonia (NH3)	30D Conc	1.0	1.14	9/1/2012
001	00610	Nitrogen, Ammonia (NH3)	7D Conc	1.5	2.12	9/1/2012
001	00610	Nitrogen, Ammonia (NH3)	7D Qty	.34	.34504	9/1/2012

The operator of record has already responded to these violations. He has increased the run time on the blowers in the aeration basin which seems to have eliminated the ammonia violations. The total suspended solids violations appear to be from the large amounts of Inflow/Infiltration (I/I) in the collection system. The village should begin evaluating the collection system and eliminating sources of I/I to help the treatment plant remain in compliance.

If there are any questions, please call me at (740) 380-5268.

Sincerely,



Jack Knapp
District Representative
Division of Surface Water

JK/dh

Enclosure

c: Gary Sollars



State of Ohio Environmental Protection Agency
Southeast District Office

Municipal NPDES Compliance Inspection Report

Section A: National Data System Coding					
Permit #	NPDES #	Month/Day/Year	Inspection Type	Inspector	Facility Type
OPA00001*GD	OH0021547	November 14, 2012	R	S	1

Section B: Facility Data			
Name and Location of Facility Inspected		Entry Time	Permit Effective Date
Clarksburg WWTP State Route 138 Clarksburg, Ohio		11:40 a.m.	July 1, 2008
		Exit Time	Permit Expiration Date
		12:10 p.m.	June 30, 2013
Name(s) and Title(s) of On-Site Representative(s)		Phone Number(s)	
Gary Sollars, Operator of Record		(740) 505-6342	
Name, Address, and Title of Responsible Official		Phone Number	
Village of Clarksburg Sue Bethel, Mayor P.O. Box 187 Clarksburg, Ohio 43115		(740) 993-4300	

Section C: Areas Evaluated During Inspection					
(S = Satisfactory; M = Marginal; U = Unsatisfactory; N = Not Evaluated; N/A = Not Applicable)					
S	Permit	S	Flow Measurement	N/A	Pretreatment
S	Records/Reports	N/A	Laboratory	N/A	Compliance Schedules
S	Operations & Maintenance	S	Effluent/Receiving Waters	S	Self-Monitoring Program
S	Facility Site Review	S	Sludge Storage/Disposal		Other
M	Collection System				

Section D: Summary of Findings (attach additional sheets if necessary)			
Please see attached letter.			
Inspector		Reviewer	
Date		Date	
12/13/12		12/12/12	
Jack Knapp Division of Surface Water Southeast District Office		Jennifer M. Witte Compliance & Enforcement Supervisor Division of Surface Water Southeast District Office	