



John E. Kasich, Governor
Mike Taylor, Lt. Governor
Scott L. Smith, Director

February 14, 2013

Fred Claugus
Central Aluminum Company
2045 Broehm Road
Obetz, OH 43207

**Re: Central Aluminum Company / Franklin County
Industrial Storm Water Permit 4GR00344*DG**

Dear Mr. Claugus:

This letter is written in regard to the storm water inspection that I conducted on February 11, 2013, at Central Aluminum Company, located at 2045 Broehm Road, in Columbus, Ohio. The inspection was conducted to determine compliance with your industrial storm water permit. You stated that your company produces aluminum extrusions. It was noted that your facility does not have a current industrial storm water permit. Your facility is required to seek storm water permit coverage, from Ohio EPA in accordance with 40 CFR 122.26, authorizing storm water discharges. The permit requires the development and implementation of a Storm Water Pollution Prevention Plan (SWPPP). The SWPPP mandates specific storm water practices, which minimize storm water contamination, associated with external operations or exposed materials. Please submit an industrial storm water permit associated with industrial activities immediately. You may obtain additional information at the following weblink: <http://epa.ohio.gov/dsw/storm/index.aspx>. The following items were noted during the inspection:

1. The roll-off dumpster located near the southwest corner of the building is still uncovered. This roll-off was uncovered and had empty drums, solid waste and metal shavings stored in the roll-off. There were also several other uncovered waste containers than contained metal filings. Please install a cover on the roll-off dumpster and all other outside waste containers. Please see attached pictures.
2. During my inspection, you could not find the company's storm water pollution prevention plan (SWP3) due to remodeling at the facility. Please insure that the company has an up-to-date SWP3 and that is reviewed annually. A log of the annual review including the reviewer's name and date should be kept in the SWP3.
3. There were empty drums stored upside down and without a lid outside on pallets. Please store empty drums upright and with a lid. Please see attached picture.
4. There was a white pipe discharging a white substance from the southeast corner of the building. Please provide me a written response stating the nature of the discharge. Please see attached picture.

Fred Claugus
Central Aluminum Company
Page -2-

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3851.

Sincerely,

A handwritten signature in black ink, appearing to read 'G. Sanders', written in a cursive style.

Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

Enclosures

ec: Greg Sanders, DSW/CDO

GS/nsm Shasta Beverages, Inc., February 11, 2013



