



John A. Kasich, Governor
Mary Taylor, Lt. Governor
Paul A. Sully, Director

March 6, 2013

Paul and Phyllis Carver
963 West Orange Road
Delaware, Ohio 43015

**Re: Storm Water Inspection at River Rock Subdivision
Delaware County
Permit Number: 4GCO00081*AG**

Dear Paul and Phyllis Carver:


This letter is written in follow up to a storm water inspection I conducted of the construction activities associated with River Rock Subdivision located at 963 West Orange Road in Delaware County on February 27, 2013. This site (specifically located at N40.17548, W83.0302) appears to be greater than one acre and is currently covered under Ohio EPA's General Storm Water Permit for Construction Activities in the Olentangy Watershed (Permit Number 4GCO00081). Based on my site observations, the following items were noted:

Sediment and Erosion Controls:

- Please continue to ensure positive drainage to the basins intended for sediment control. Specifically, the basins along the western perimeter.
- All sediment basins must be maintained once sediment accumulation exceeds 50 percent of the design capacity.
- All disturbed areas must be protected from erosion if they are dormant in excess of 21 days. Given the time of the year, a crimped mulch cover or equivalent is expected once the fill activities are completed. It appears fill activities have ceased for portions of the site. Temporary cover is expected.
- The permit issued for the fill activities only may be terminated at this time.

If you have any question regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,


For HK
Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/hsm River Rock 2-27-2013