



December 18, 2012

Steve Hiemberger  
Mondi Akronil  
3165 Wilson Road  
Lancaster, OH 43130

Re: Akrosil, Fairview County  
Industrial Storm Water Permit AGR00038720

Dear Mr. Hiemberger:

This letter is written in regard to the storm water inspection that I conducted on December 12, 2012, at Akrosil, located at 3165 Wilson Road, in Lancaster, Ohio. The inspection was conducted to determine compliance with your industrial storm water general permit. Your company manufactures silicone-coated release liners for pressure sensitive products. The following items were noted during the inspection:

1. You will need to submit an industrial storm water notice of intent renewal application. Your previous permit expired several months ago.
2. The haptene and toluene storage tanks have secondary containment. The loading are for the storage tank have a contained area with a gate valve. The gate valve is closed during the unloading of the the haptene and toluene.
3. Your facility had a storm water pollution prevention plan (SWP3) and spill prevention plan. Spill kits were located through-out the facility. The SWP3 should be signed and dated. It should also be reviewed annually.
4. There was empty drum storage outside of the facility. All drums had a lid and were stored upright. No staining or discharge on the pavement near the drums was observed.
5. You state that you complete an environmental audit inspection every three months and inspect the secondary containment areas weekly. You discussed the protocol for discharging the storm water and/or wastewater from the diked areas.

Steve Hiemberger  
Mondi Akrosil  
Page -2-

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3974.

Sincerely,



Gregory L. Sanders  
Environmental Engineer  
Division of Surface Water  
Central District Office

cc: Mike Smith, Mondi Akrosil

cc: Greg Sanders, DSW/CDO

GS/nsm Akrosil, December 13, 2017

