



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Susan L. Meiby, Director

April 11, 2013

Brad Rucker
Coughlin Automotive Properties of Circleville
PO Box 1474
Pataskala, OH 43062

**Re: Storm Water Inspection at Coughlin Automotive Properties of Circleville
Licking County, Permit # 4GC03613*AG**

Dear Mr. Rucker:

This letter is written regarding a storm water inspection I conducted at Coughlin Automotive located in Heath, Ohio on April 4, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Post Construction Requirements:

- **Please forward to my attention, the chosen post construction measures implemented at this site. Please include all design criteria for evaluation. I noted the small basin towards the northern end of the property, however I was unclear if the southern end was properly addressed.**

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Coughlin automotive Heath 4-4-2013