40 years and moving forward

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

May 24, 2013

James Bauer
Maronda Homes, Inc. of Ohio
3811 Twin Creek Drive
Columbus, OH 43204

Re: Georges Creek, Fairfield County

Dear Mr. Bauer

This letter is written regarding the storm water inspection that I conducted on May 21, 2013, at Georges Creek in Fairfield County. I understand that these construction activities are currently covered under the General Storm Water Permit Associated with Construction Activities. There was active construction during my inspection and several homes were under construction. The purpose of the inspection was to ensure continued compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following:

Sediment and Erosion Controls:

- Most of the sites had erosion controls installed. However, a few sites did not have erosion controls installed. Also, several of the sites needed to have the erosion controls maintained. Please install and maintain erosion controls at all active sites. Please see attached pictures.

- Please be aware that the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days. There were several sites that appeared to be at or near final grade. Please see attached pictures.

If you have any questions regarding this letter or my inspection, please do not hesitate to call me at our Central District Office at (614) 728-3851.

Sincerely,

Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

Enclosure

c: Jim Ohlin, Ryan Homes

GS/nsm Georges Creek, May 21, 2013

Georges Creek
Install erosion controls
Stabilize barren area
Walnut Creek Watershed
May 21, 2013
Photo by: Greg Sanders