



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

May 22, 2013

Ms. Christy Fielding
Xenia Community School District
578 E Market St.
Xenia, OH 45385

RE: Spring Hill Elementary School; NPDES Permit # 1GC04532*AG; Construction Site Inspection

Dear Mr. Oberer:

On Monday, May 20, 2013, I inspected the Spring Hill Elementary School project to determine compliance with its NPDES construction site storm water discharge permit. I walked the property, and then met with you at the Xenia Board of Education offices.

Based on my observations and review of the provided storm water pollution prevention plan there were no obvious violations of the project's storm water discharge permit.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "notice of termination" (NOT) form found at [http://www.epa.ohio.gov/Portals/35/permits/General NOT.pdf](http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf) must be completed and sent to the address shown on page 2 of the NOT instructions.

If you have questions regarding this letter you can contact me at 937-204-1003, or via email at eric.damian@epa.ohio.gov.

Sincerely,

Eric Damian
Storm Water Group
Division of Surface Water

ED/kb

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: ESD

Visit date: 5/20/13 Permit # 1GC04532*AG

Site Name: Spring Hill Elem. School

Site Address: 860 Ormsby Dr. Xenia, OH 45385

People contacted on site (attach business cards): Christy Fielding

Their phone and e-mail: 937-562-9002 cfielding@xenia.k12.oh.us

1. Did you see the following on site?

| ITEM | Yes/No | Not requested | Comments |
|--------------------------------------|--------|---------------|--------------------|
| NOI | | ✓ | |
| Coverage letter | | ✓ | |
| SWP3 | ✓ | | provided via email |
| Inspection records | | ✓ | |
| Contractor & Subs signature document | | ✓ | |

2. Acreage disturbed (circle): < 1 acre >1 but <5 acres >5 but <10 acres >10 acres ??

3. Site status,; Clearing/grubbing Rough grading Storm sewers in Streets in
 Utilities installed Final grade Final stabilization

4. Are BMPs needed on site? not necessary until demolition complete

5. Are BMPs on site effective? All Some None No BMPS

Explain: _____

6. What post construction controls are shown on the SWP3? removal of all sediment and
erosion control methods and
reseeding any areas disturbed
by their removal

7. Were photos taken and saved? no

8. Was an NOV issued? no

Notes: