



Mike DeWine, Governor
Larry Taylor, Lt. Governor
John J. Malley, Director

May 17, 2013

Andy Finke
Prologis-The Gloal Distribution Solution
7048 Fairfield Business Drive
Fairfield, Ohio 45014

**Re: Construction Storm Water Inspection at Prologis in Etna, Ohio
Permit Number: 4GC004067*AG**

Dear Mr. Finkle:

This letter is written regarding a storm water inspection I conducted at Prologis located in Etna, Ohio on April 30, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- The outlet structure of the main sediment pond is NOT properly sealed. It was obvious the storm water was discharging around and NOT through the pipe. This has a direct impact on sediment storage volume and must be repaired. The pond is located directly adjacent to US Route 40.
- It appears positive drainage is established for the majority of the site to a sediment pond with the exception of the western perimeter. Please re-establish the western sediment pond. The pond must accommodate the required sediment storage volume
- Temporary erosion protection is required for all affective areas which remain idle in excess of 21 days. Self inspection logs must be maintained to ensure this condition is not violated

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Prologis 4-30-2013