



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

May 30, 2013

Re: Ross County
Mountain View MHP
Compliance Evaluation Inspection
NPDES Permit OGS00020*BG
Correspondence (PWW)

Mr. Joe Corcoran
146 Walnut Creek Road
Chillicothe, Ohio 45601

Dear Mr. Corcoran:

On May 16, 2013, I conducted a compliance inspection of the Mountain View MHP wastewater treatment plant (WWTP). The purpose of the inspection was to determine the facility's compliance status with the terms and conditions of NPDES permit number OGS00020*BG.

The following observations led to the unsatisfactory rating for Records/Reports, Operations and Maintenance, and Laboratory:

1. The Mountain View MHP that you recently purchased has a wastewater treatment plant that is covered under NPDES permit number OGS00020*BG. The permit should have been transferred to you prior to the sale. Please fill out a Notice of Transfer form and submit it to this office as soon as possible. The form can be found at: http://epa.ohio.gov/Portals/35/permits/NPDES_Transfer.pdf
2. The facility is not under the supervision of a certified wastewater operator. The facility needs to hire a contract operator immediately and fill out an operator of record notification form. The form can be found at: http://epa.ohio.gov/portals/28/documents/opcert/Operator_of_Record_Notification_Form.pdf
3. The facility has not submitted any Discharge Monitoring Reports (DMR) since permit number OGS00020*BG went into effect.
4. There did not appear to be any electric service being supplied to the wastewater plant. The electric needs to be restored so the plant can be properly operated.

Please provide a written response to these comments within 10 days upon receipt of this letter. Failure to do so will result in an enforcement referral to our legal department. If you have any questions about the inspection please call me at (740) 380-5268.

Sincerely,



Jack Knapp
District Representative
Division of Surface Water

JK/dh

Enclosure



State of Ohio Environmental Protection Agency
Southeast District Office

Municipal NPDES Compliance Inspection Report

Section A: National Data System Coding					
Permit #	NPDES #	Month/Day/Year	Inspection Type	Inspector	Facility Type
0GS00020*BG	OHGS00036	May 16, 2013	C	S	1

Section B: Facility Data		
Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Mountain View Mobile Home Park Rocky Road Chillicothe, Ohio	11:00 a.m.	December 1, 2011
	Exit Time	Permit Expiration Date
	11:15 a.m.	December 31, 2014
Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)	
none		
Name, Address, and Title of Responsible Official	Phone Number	
Joe Corcoran, Owner 146 Walnut Creek Road Chillicothe, Ohio 45601	(740) 775-1282	

Section C: Areas Evaluated During Inspection					
(S = Satisfactory; M = Marginal; U = Unsatisfactory; N = Not Evaluated; N/A = Not Applicable)					
S	Permit	S	Flow Measurement	N/A	Pretreatment
U	Records/Reports	U	Laboratory	N/A	Compliance Schedules
U	Operations & Maintenance	U	Effluent/Receiving Waters	U	Self-Monitoring Program
U	Facility Site Review	S	Sludge Storage/Disposal		Other
S	Collection System				

Section D: Summary of Findings (attach additional sheets if necessary)			
Please see attached letter.			
Inspector		Reviewer	
Date		Date	
5/31/13		5/31/13	
Jack Knapp District Representative Division of Surface Water Southeast District Office		Jennifer M. Witte Compliance & Enforcement Supervisor Division of Surface Water Southeast District Office	