



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 4, 2013

Re: Washington County
Hervida 4-H Camp, Inc.
Compliance Evaluation Inspection
NPDES Permit OPR00107*DD
Application OH0114898
Correspondence (PWW)

Mr. Don Eifler, Facilities Manager
Hervida 4-H Camp, Inc.
220 Davis Avenue
Marietta, Ohio 45750

Dear Mr. Eifler:

On May 20, 2013, a Compliance Evaluation Inspection was conducted at the Hervida 4-H Camp. The purpose of the inspection was to determine the facility's compliance with its National Pollutant Discharge Elimination System (NPDES) Permit. I spoke with Don Eifler and Sam Booker representing Hervida during the inspection.

The facility has some violations of its NPDES Permit for Total Suspended Solids and Chlorine Residual. The facility is planning on relocating the discharge pipe into the third lagoon to help address the Total Suspended Solids in the discharge. Some modifications were done to slow the flow through the tablet dechlorinator which appears to have addressed the chlorine violations.

In conclusion, Hervida 4-H Camp appeared to be in compliance with its NPDES Permit at the time of the inspection, due to Hervida taking the necessary steps to return to compliance.

If you have any questions, feel free to contact me at (740) 380-5434.

Sincerely,

A handwritten signature in blue ink, appearing to read "Stephen Wells", is written over a light blue horizontal line.

Stephen Wells
District Representative
Division of Surface Water

SW/dh

Enclosure



State of Ohio Environmental Protection Agency
Southeast District Office

Municipal NPDES Compliance Inspection Report

Section A: National Data System Coding

Permit #	NPDES #	Month/Day/Year	Inspection Type	Inspector	Facility Type
0PR00107*DD	OH0114898	May 20, 2013	C	S	1

Section B: Facility Data

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Hervida 4-H Camp Junction of Waterford Township Roads #107 and 108 Watertown, Ohio	1:30 p.m.	August 1, 2012
	Exit Time	Permit Expiration Date
	2:15 p.m.	July 31, 2017
Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)	
Sam Booker, Contract Operator	(740) 376-7431	
Name, Address, and Title of Responsible Official	Phone Number	
Don Eifler, Facilities Manager Hervida 4-H Camp, Inc. 220 Davis Avenue Marietta, Ohio 45750	(740) 376-7431	

Section C: Areas Evaluated During Inspection

(S = Satisfactory; M = Marginal; U = Unsatisfactory; N = Not Evaluated; N/A = Not Applicable)

S	Permit	S	Flow Measurement	N/A	Pretreatment
S	Records/Reports	S	Laboratory	N/A	Compliance Schedules
S	Operations & Maintenance	S	Effluent/Receiving Waters	S	Self-Monitoring Program
S	Facility Site Review	N/A	Sludge Storage/Disposal	--	Other
N/A	Collection System				

Section D: Summary of Findings (attach additional sheets if necessary)

See attached letter.

Inspector	Reviewer
 Stephen Wells Division of Surface Water Southeast District Office	 Jennifer M. Witte Compliance & Enforcement Supervisor Division of Surface Water Southeast District Office
6/4/13 Date	6/4/13 Date