



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 5, 2013

Mr. Jim Leslie
Harrison Wastewater Treatment Plant
10999 Campbell Road
Harrison, Ohio 45030

**RE: NPDES Permit 1PC00002*ID / OH0021440
Reconnaissance Inspection**

Dear Mr. Leslie:

I stopped by the wastewater treatment plant on May 30, 2013 with four college interns working for Ohio EPA this summer. We performed a reconnaissance inspection of the operations and effluent quality. These areas were rated satisfactory. Attached is a copy of my report. If you have any questions regarding this site visit, please contact me by phone at (937) 285-6101 or by email at mary.osika@epa.ohio.gov.

Sincerely,

Mary Osika
Environmental Specialist II
Division of Surface Water

MO/tb

Enclosure

Section A: National Data System Coding

Permit Number	NPDES Number	Inspection Date (dd/mm/yy)	Inspection Type	Inspector	Facility Type
1PC00002*ID	OH0021440	5/30/2013	Recon.	State	Public

Section B: Facility Data

Name and Location of Facility Inspected:	Entry Time	Permit Effective Date
City of Harrison Wastewater Treatment Plant 10999 Campbell Road Harrison, Ohio	10:00 am	August 1, 2008
	Exit Time	Permit Expiration Date
	10:38 am	January 31, 2013
Name(s) and Titles of On-Site Representative(s)	Phone Number(s)	
Bob Haas, Operator	(513) 367-3725	
Gene Allen, Operator	(513) 367-3725	
Name, Title and Address of Responsible Official:	Phone Number	
Jim Leslie, Director of Utilities City of Harrison WWTP 10999 Campbell Road Harrison, Ohio 45030	(513) 367-2111	



Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, NA = Not Applicable)

Permit	Flow Measurement	Pretreatment
Records/Reports	Laboratory	Compliance Schedules
S Operations & Maintenance	S Effluent/Receiving Waters	Self-monitoring Program
S Facility Site Review	S Sludge Storage/Disposal	Other
Collection System		

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

Inspected facility due to being in the area. Facility was pressing sludge for removal by Rumpke. Facility operations and effluent quality looked satisfactory. Provided training to four college interns working for Ohio EPA by showing them a facility with Activated Sludge treatment using oxidation ditches.

Name and Signature of Inspector(s) Mary Osika 	Agency / Office / Telephone Ohio EPA / Southwest District Office / (937) 285- 6101	Date 6/5/2013
Name and Signature of Reviewer Martyn Burt 	Agency / Office / Telephone Ohio EPA / Southwest District Office / (937) 285- 6034	Date 6/6/2013