

John E. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

June 5, 2013

Dave Warren  
McDonald's USA LLC  
2 Easton Oval, Suite 200  
Columbus, OH 43219

**Re: Storm Water Inspection at McDonalds Restaurant-Obetz / Franklin County  
Permit Number: 4GC04043\*AG**

Dear Mr. Warren:

This letter is written in follow-up to a construction storm water inspection by Brittany Turner of the Ohio EPA, at McDonalds Restaurant - Obetz located at 5090 Groveport Road, Obetz on May 31, 2013. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

**Sediment and Erosion Controls:**

- The silt fence on the southeast portion of the site has failed and will require maintenance at this time (See Figure 1 & 2).
- The spill noted in Figure 3 should be properly collected and disposed of in order to ensure compliance with the Ohio EPA General Storm Water Permit.
- Please be aware that the General Permit indicates that all sediment controls will be inspected and maintained every seven days or within 24 hours of a precipitation event equal to or greater than 0.5 inches. A log of inspection must be maintained on site for the agency to review.

**Post Construction Requirements:** The General Storm Water Permit requires specific post construction water quality treatment for all sites. Guidance regarding the post construction mandates can be found at:

<http://www.epa.state.oh.us/dsw/storm/CGPPCQA.aspx>. Please submit to my attention (email preferred at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us)) which practice will be installed at this site to ensure compliance with the General Permit. Please include all design criteria with your submittal.

Dave Warren  
McDonald's USA LLC  
Page 2


If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,


A handwritten signature in black ink, appearing to read 'Harry Kallipolitis', with a long horizontal flourish extending to the right.

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm McDonalds Restaurant Obetz 5-31-2013



**Figure 2: Silt fence on southeast corner requires maintenance**



**Figure 1: Silt fence on southeast corner requires maintenance**



Figure 3: Oil spill requires proper disposal