



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 6, 2013

Estate of Marilyn Schnicke
c/o Bob and Lisa Crable, Executor
P. O. Box 385
Loveland, Ohio 45140

**RE: Miamiview Estates MHP WWTP
5825 State Route 128, Cleves
NPDES Permit 1PV00018*FD / OH0049824
Compliance Evaluation Inspection**

Dear Mr. and Mrs. Crable:

On May 31, 2013, I inspected the sewage treatment system at Miamiview Estates Mobile Home Park. Attached is a copy of my inspection report. It does contain a Notice of Violation regarding the effluent limit violation that occurred during the review period of March 2012–April 2013. The violation has not occurred since the problem was investigated and no response to this letter is necessary.

The sewage treatment system was satisfactory at the time of inspection. If you have any questions regarding the compliance review or inspection, please contact me at (937) 285-6101.

Sincerely,

A handwritten signature in cursive script, appearing to read 'Mary Osika', is written over a light blue horizontal line.

Mary Osika
Environmental Specialist
Division of Surface Water

MO/tb

Enclosure

ec: Bob Reckers, Winelco



State of Ohio Environmental Protection Agency
Southwest District Office

NPDES Compliance Inspection Report
Semi-Public Sewage Disposal Inspection Form

Section A: National Data System Coding

Permit #	NPDES#	Month/Day/Year	Inspection Type	Inspector	Facility Type
1PV00018*FD	OH0049824	5/31/2013	Compliance	State	Semi-public

Section B: Facility Data

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Miamiview Estates MHP WWTP 5825 State Route 128 Cleves, Ohio	9:45 am	September 1, 2010
	Exit Time 10:10 am	Permit Expiration Date August 31, 2015
Name(s) and Title(s) of On-Site Representatives	Phone Number(s)	
Name(s), Address and Title(s) of Operator of Record	Phone Number(s)	
Bob Reckers, Operator 3 Winelco 6141 Centre Park Drive West Chester, Ohio 45069	(513) 265-1900	
Name, Address and Title of Responsible Official	Phone Number	
Estate of Marilyn Schnicke c/o Bob and Lisa Crable, Executor P.O. Box 354 Loveland, Ohio 45140	(513) 353-2442	

Ohio EPA Inspector	Ohio EPA Reviewer
Mary Osika Division of Surface Water Southwest District Office	Martyn Burt Compliance & Enforcement Supervisor Division of Surface Water Southwest District Office
Date	Date

Permit # : 1PV00018*FD

NPDES #: OH0049824

MIAMIVIEW ESTATES MHP WASTEWATER TREATMENT PLANT -

Average Daily Design Flow:	40,00 Gallons/Day
Plant Serves:	Mobile Home Park
Average Daily Flow: (Period of Review):	1,982 Gallons/Day (January 2012 – April 2013)
Method of flow monitoring:	meter
Type of alarms for plant:	visual

Pretreatment

Type of Pretreatment: **Comminutor**
Does the Trash Trap need pumped: **N/A**
Maintenance of pretreatment components is: **Fair**

Comments/Status:

The comminutor appeared to be inoperable. What is the status of repair?

**Secondary Treatment
(Aeration)**

Color of sludge: **Medium Brown**
Quality of Sludge: **Medium**
Foam: **None present**
Odor: **No objectionable odor present**

	Yes	No		Yes	No
Aeration is taking place	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Plant is septic	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Blowers are operating	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Blowers are on a timer	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Skimmers are operating	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Plant is flooded	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Diffusers are operating	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Grating is present	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Sludge return is operating	<input checked="" type="checkbox"/>	<input type="checkbox"/>			

Maintenance of aerating equipment is...**Good**

Comments/Status:

**Secondary Treatment
(Settling)**

Clarity: **Clear**
Condition of Weir: **Excessive Algae/Solids Build Up**

Permit # : 1PV00018*FD

NPDES #: OH0049824

Weir is level: **Yes**
Effluent in weir: **Clear**
Clarifier walls need scraped: **No**

Overall maintenance of settling components is: **Good**

Comments/Status:

Algae is growing on the weir and should be removed.

Tertiary Treatment

	Yes	No		Yes	No
Surface sand Filters: Slow	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Subsurface	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Distribution box operating	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Beds alternated	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Are filters ponding/flooding	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Beds raked	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Sand filters overgrown	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Chlorination present	<input type="checkbox"/>	<input checked="" type="checkbox"/>
UV present	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Dechlorination present	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Overall maintenance of components is: **Good**

Comments/Status:

Solids scraped from sand filters appear to be dumped on the ground. The solid waste must be disposed in a trash receptacle for removal.

Sludge Handling/Storage Disposal

Hauler name: Winelco
Disposal Site: MSD-Mill Creek WWTP; NPDES 1PM00001*LD
Sludge wasted from: sludge holding tank
How often is sludge wasted: periodically
Sludge drying beds: **No** Sludge holding tank: **Yes**

Overall maintenance of components is: **Good**

Comments/Status:

32,000 gallons of sludge hauled away for disposal during 2012.

Plant Discharge

Discharge point is a: **Stream**
Name of discharge point: ditch tributary to Great Miami River
Discharge is visible: **No** Quality of Effluent: **Clear**

Comments/Status:

Viewed effluent in clarifier and sand filters.

Permit # : 1PV00018*FD

NPDES #: OH0049824

Operator Requirements

Operator Class requirement: I Comply: yes

Operator Log Book: No Comments: Did not find log book in the WWTP, manager's office closed

Records checked: None Comments: Recommend mailbox for log book, daily recordings and maintenance records at the WWTP (inside)

Sampling Quality Control

General Lab Criteria: N/E

Contract Lab: Winelco

Any onsite analysis: yes

Parameters: Temperature, Dissolved Oxygen, pH

Discharge Monitoring Reports review

Compliance Review Period: March 2012 – April 2013

Comply with the permit conditions: No

Notice of Violation included: Yes

Comments: Non-compliance notification was received from the operator for the effluent limit violation. Cause is unknown or possible lab error.

Notice of Violation

Please be advised that failure to comply with the effluent limitations or reporting requirement of your NPDES permit may be cause for enforcement action pursuant to the Ohio Revised Code Section 6111.

<u>Parameter</u>	<u>Date</u>	<u>Limit</u>	<u>Value Reported</u>
Total Suspended Solids	3/22/2012	18 mg/l	21 mg/l