



John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Eric J. Kelly, Director

June 11, 2013

Mark Waller  
South-Western City Schools  
3805 Marlene Drive  
Grove City, OH 43123

**Re: Construction Storm Water Inspection at Alton Hall Elementary School / Franklin County.  
Permit Number: 4GCD00093\*AG**

Dear Mr. Waller:

This letter is written regarding a storm water inspection conducted by Sam Marotta and Paul Hafner, of the Ohio EPA at Alton Hall Elementary School located at 1000 Alton Road on June 6, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

**Sediment and Erosion Control:**

- Ensure all water has positive flow to the onsite sediment pond prior to the storm sewer installation.
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days. This directly applies to the stockpiles noted onsite.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm Alton Elementary School 6-6-13