



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 14, 2013

Mr. Larry Reinsmith
City of Wilmington
69 N. South Street
Wilmington, Ohio 45177

**RE: Former Textron Inc. Property; NPDES Permit 1GC03949*AG
Construction Site Inspection**

Dear Mr. Reinsmith:

On Tuesday, June 11, 2013, I inspected the Former Textron Inc. property project located at 360 and 474 S. Nelson Avenue, Wilmington, Ohio, to determine compliance with its NPDES construction site storm water discharge permit. I walked the property, but did not meet with anyone while at the site.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review sediment control inspection logs or the site's storm water pollution prevention plan (SWPPP). I noticed that there were no sediment and erosion controls on the site. From what I was able to see, there was no need for such controls. However, I request that you please, along with your written response to this letter, provide a copy of the site's SWP3 for review by June, 28 2013.

As a reminder, please note that when construction is complete and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "Notice of Termination" (NOT) form can be found at [http://www.epa.ohio.gov/Portals/35/permits/General NOT.pdf](http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf). It must be completed and sent to the following address:

Ohio Environmental Protection Agency
General Permit Program
P.O. Box 1049
Columbus, OH 43216-1049

Former Textron Property – Construction Site Inspection
NPDES Permit 1GC03949*AG
June 14, 2013
Page 2

If you have questions regarding this letter you can contact me at (937) 285-6357 or via email at eric.damian@epa.ohio.gov.

Sincerely,

A handwritten signature in black ink, appearing to read 'Eric Damian', with a horizontal line extending to the right.

Eric Damian
Storm Water Group
Division of Surface Water

ED/tb

Enclosure: Inspection Form

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: ESD Visit date: 6/11/13 Permit # 1GC03946*AG

Site Name: Former Textron Inc. Property

Site Address: 360 & 474 S. Nelson Ave

People Contacted On Site: none

Phone: n/a E-mail: n/a

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI			✓	
Coverage Letter			✓	
SWP3			✓	<u>request in letter</u>
Inspection Records			✓	
Contractor & Subs signature document			✓	

2. Acreage Disturbed: 2.1

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in
 Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: no

5. Are BMPs effective? All Some None No BMPs

Explain: no bmp's needed from observation

6. What post construction controls are shown on the SWP3? n/a

7. Were Photos taken & saved? no 8. Was an NOV issued? no

Additional notes/comments:
