



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

Re: Ottawa County
Middle Bass Island
East Point Villas
NPDES Permit

June 18, 2013

Mr. Greg Ridge
East Point Villas
10688 West State Route 18
Fostoria, Ohio 44830

Dear Mr. Ridge:

On June 4, 2013, an inspection was made of the wastewater treatment facilities serving the East Point Villas on Middle Bass Island. At the time of my visit, all major components were in operation; however, no discharge was taking place, as the effluent level was still well below the outlet of the chlorine contact tank. The sand filters remain well kept; both chlorine and dechlorination tablets were in the tube feeders. The contact tank contained debris from the winter and needs to be cleaned.

National Pollutant Discharge Elimination System (NPDES) discharge monitoring reports are being received in a timely manner. A review for last season indicated effluent violations during the quarterly June 2012 reporting period, and compliance the remainder of the year. I appreciate your support in ensuring this facility receives proper operation and maintenance and look forward to your continuing cooperation this year.

Enclosed is my completed inspection report. If you have any questions, please call me at (419) 373-3020 or email at rick.zuzik@epa.ohio.gov.

Sincerely,

A handwritten signature in black ink, appearing to read 'R. Zuzik', written over a horizontal line.

Richard A. Zuzik, MSE
Division of Surface Water

/jlm

Enclosure

pc: Ottawa County Health Department
Eastwood Environmental

ec: Tracking

Facility Name: East Point

Process	# Units	Unit	If Needed - Description and Comments
Preliminary	1	Trash Trap	Pumping Frequency
		Grease Trap	Pumping Frequency
		Bar Screen	
		Comminutor	
	1	Flow Equalization	
Aeration Equipment		Plant Timer <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Cycle Time:
	2	Motor / Blower Unit	
Secondary Treatment	1	Aeration Tank	Color: Adequate Aeration Y <input checked="" type="checkbox"/> N
Final Settling	1	Clarifier	
	1	Sludge Return	In <input checked="" type="checkbox"/> Out
	1	Surface Skimmer	In <input checked="" type="checkbox"/> Out
		Fixed Media Clarifier	
Tertiary Treatment	2	Surface Sand Filter	
		Polishing Pond	
		Other	
Disinfection	1	Contact Tank	Needs cleaned
	1	Chlorine Tube Feeder	
	1	Dechlorination Tube Feeder	<i>W</i> <i>W</i>
		Ultraviolet (UV)	
Flow Metering		Elapsed Pump Time	
		Recorder (continuous total)	
Pumps		Raw Wastewater (type)	
		Sand Filter Effluent Dosing	
Sludge Handling		Aerated Storage Tank	
		Sludge Drying Bed	
Sludge Disposal		Municipal POTW	
		Landfill	
		Land Application	
Advanced Treatment		Post Aeration	
		Spray Irrigation	
		Other	