



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 13, 2013

Michael Lilly
Jackson Township
3756 Hoover Road
Grove City, OH 43123

Re: **Construction Storm Water Inspection at Jackson Township Fire Station #204 / Franklin County. Permit Number: 4GC03999 *AG**

Dear Mr. Lilly,

This letter is written regarding a storm water inspection conducted by Sam Marotta and Elizabeth Pleta, of the Ohio EPA at Jackson Township Fire Station #204 located at 2050 Holton Road on June 3, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Our staff observed an area of concrete disposal that lacked proper containment (See Figure 1). If future onsite disposal is required, containment measures such as a pit impoundment is expected. A washout containment area must be established to ensure compliance with the Ohio EPA's General Storm Water Permit.
- Please ensure ensure positive flow of storm water from the site to the basins intended for sediment control during all phases of construction.

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Jackson Township Fire Station #204 6-3-13