Ohio EPA
40 years and moving forward

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 12, 2013

Ms. Virginia Rammel
Milton-Union Exempted Schools District
112 South Spring Street
West Milton, OH 45383

RE: Milton-Union High School; NPDES Permit #1GC04310*AG; Compliance Inspection Findings

Dear Ms. Rammel:

On Tuesday, June 11, 2013, I inspected the Milton-Union High School project in West Milton, Ohio, to determine compliance with the site's NPDES construction site storm water discharge permit. No one was present at the site at the time of the inspection.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review the sediment control inspections logs or the site's storm water pollution prevention plan before my inspection. The site has been permanently stabilized with grass seed and straw.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "Notice of Termination" (NOT) form can be found at http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf. It must be completed and sent to the following address:

Ohio Environmental Protection Agency
General Permit Program
P.O. Box 1049
Columbus, OH 43216-1049

No response to this letter is needed.

If you have any questions regarding the NPDES permit you can contact me at (937) 204-1002 or via email james.schwieterman@epa.ohio.gov.

Sincerely,

James Schwieterman
Storm Water Group
Division of Surface Water

JS/tb

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS **Visit date:** / / / **Permit #** 1GC04310*AG

Site Name: Milton-Union Exempted Schools District

Site Address: 221 S. Jefferson St.

People Contacted On Site: None

Phone: _____ E-mail: _____

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI				No one on site
Coverage Letter				
SWP3				
Inspection Records				
Contractor & Subs signature document				

2. Acreage Disturbed: 2.218

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in

Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: NO

5. Are BMPs effective? All Some None No BMPs

Explain: Grass Seed + Straw

6. What post construction controls are shown on the SWP3? N/A

7. Were Photos taken & saved? NO 8. Was an NOV issued? N/A

Additional notes/comments:

Submit an NOT