



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 18, 2013

Ms. Mary Meyers
Village of Verona
100 W Main Street
Verona, OH 45378

**RE: Swamp Creek Storm Outlet; NPDES Permit # 1GC04379*AG
Compliance Inspection Findings**

Dear Mrs. Meyers:

On Thursday, June 13, 2013, I inspected the Swamp Creek Storm Outlet project in Verona, Ohio to determine compliance with the site's NPDES construction site storm water discharge permit. No one was present at the site at the time of the inspection.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. The current erosion controls meet requirements under the NPDES permit. I did not review the sediment control inspections logs or the site's storm water pollution prevention plan before my inspection.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "Notice of Termination" (NOT) form can be found at http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf. It must be completed and sent to the following address:

Ohio Environmental Protection Agency
General Permit Program
P.O. Box 1049
Columbus, OH 43216-1049

No response to this letter is needed.

If you have any questions regarding the NPDES permit you can contact me at (937) 204-1002 or via email james.schwieterman@epa.ohio.gov.

Sincerely,

James Schwieterman
Storm Water Group
Division of Surface Water

JS/tb

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 6/13/13 Permit # 1GC04377-AG

Site Name: SWAMP CREEK Storm Outlet

Site Address: State Street to Swamp Creek

People Contacted On Site: _____

Phone: _____ E-mail: _____

1. Did you see the following on site?

| ITEM | YES | NO | Not Requested | Comments |
|--------------------------------------|-----|----|---------------|----------|
| NOI | | | / | |
| Coverage Letter | | | / | NO ONE |
| SWP3 | | | / | ON SITE |
| Inspection Records | | | / | |
| Contractor & Subs signature document | | | / | |

2. Acreage Disturbed: 4

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in
 Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: NO

5. Are BMPs effective? All Some None No BMPs

Explain: _____

6. What post construction controls are shown on the SWP3? Storm water system

from Verona leads to Storm water Detention Basin before leaving the

7. Were Photos taken & saved? Yes 8. Was an NOV issued? NO Storm outlet into Swamp creek

Additional notes/comments: