



John Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott L. Smith, Director

June 24, 2013

Steve Gutkowski  
V&S Columbus Galvanizing  
987 Buckeye Park Road  
Columbus, OH 43207

**Re: V&S Columbus Galvanizing / Franklin County  
General Storm Water Permit #4GC03801\*AG**

Dear Mr. Messler:

This letter is written in follow-up to a construction storm water inspection that I conducted on June 19, 2013, at V&S Columbus Galvanizing, located at 987 Buckeye Park Road, in Columbus, Ohio. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following:

**Sediment and Erosion Controls:**

- There were two small areas of active construction at the site during the inspection. However, most of the site was at final grade and there was an attempt at stabilizing the barren areas. There were still barren areas that needed to be stabilized. Please be aware that the barren areas will need to be re-seeded.
- It is recommended that the garbage dumpster be covered. Dumpsters that contain scrap metal (without cutting fluids), cardboard-only or wooden pallets, do not need to be covered.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851.

Sincerely,

Gregory L. Sanders  
Environmental Specialist  
Division of Surface Water  
Central District Office

ec: Greg Sanders, DSW/CDO

GS/nm V&S Columbus Galvanizing, June 19, 2013