



John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

June 27, 2013

Mr. Scott Gilbert  
Miamisburg City School  
540 E. Park Avenue  
Miamisburg, OH 45342

**RE: Miamisburg High School Soccer Field; NPDES Permit #1GC04594\*AG  
Compliance Inspection Findings**

Dear Mr. Gilbert:

On Wednesday, June 26, 2013, I inspected the Miamisburg High School Soccer Field site in Miamisburg, Ohio, to determine compliance with the site's NPDES construction site storm water discharge permit. No one was present at the site during the inspection.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review the sediment control inspections logs or the site's storm water pollution prevention plan before my inspection. Inspection records of the erosion control BMPs are required to be kept on the construction site.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. The "Notice of Termination" (NOT) form can be found at [http://www.epa.ohio.gov/Portals/35/permits/General\\_NOT.pdf](http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf). It must be completed and sent to the following address:

Ohio Environmental Protection Agency  
General Permit Program  
P.O. Box 1049  
Columbus, OH 43216-1049

If you have any questions regarding the NPDES permit, you may contact me at (937) 204-1002 or via email [james.schwieterman@epa.ohio.gov](mailto:james.schwieterman@epa.ohio.gov).

Sincerely,

James Schwieterman  
Storm Water Group  
Division of Surface Water

JS/tb

Enclosed: Inspection Sheet

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 6/26/2031 Permit # 16C04594-A6

Site Name: Miamisburg High School Soccer Field

Site Address: 1860 Belvo Road Miamisburg, OH Mont. Co

People Contacted On Site: \_\_\_\_\_

Phone: \_\_\_\_\_ E-mail: \_\_\_\_\_

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI			✓	
Coverage Letter			✓	
SWP3			✓	
Inspection Records			✓	
Contractor & Subs signature document			✓	

2. Acreage Disturbed: 1.867

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in  
 Streets in Utilities installed Final Grade Final stabilization

4. Are BMPs needed: NO

5. Are BMPs effective? All Some None No BMPs

Explain: Flat, small field surrounded by grass

6. What post construction controls are shown on the SWP3? \_\_\_\_\_

7. Were Photos taken & saved? NO

8. Was an NOV issued? NO

Additional notes/comments: