



John E. Kasicki, Governor
Libby Taylor, Lt. Governor
Scott C. Kully, Director

July 1, 2013

John Johnston
John D Johnston Architects
3955 Montgomery Road
Cincinnati, OH 45212

**Re: Construction Storm Water Inspection at United Dairy Farmers / Franklin County
Permit Number: 4GC03984 *AG**

Dear Mr. Johnston:

This letter is written regarding a storm water inspection conducted by Brittany Turner and Elizabeth Pleta of the Ohio EPA at United Dairy Farmers located at Southwest Corner of U.S. Route 62 and Ridenour Road, Gahanna on June 4, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- This site fails to meet the minimum standards set by the Ohio EPA General Storm Water Permit. Please re-establish the sediment controls along the perimeter to minimize sediment laden runoff (See Figure 1).
- The entrance of the site must be stabilized to minimize off site vehicle tracking (See Figure 2).

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm United Dairy Farmers 6-17-2013



Figure 1: Straw waddle maintenance required on site



Figure 2: Entrance stabilization required