



John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

July 9, 2013

Mr. Leigh Williams  
Miami County Commissioners  
201 West Main Street  
Troy, Ohio 45373

**RE: MIA-CR86-2.36 (PID 83349); NPDES Permit #1GC04224\*AG;  
Compliance Inspection Findings**

Dear Mr. Williams:

On Wednesday, July 3, 2013, I inspected the MIA-CR86-2.36 (PID 83349), Bradford-Bloomer Bridge site near Bradford, Ohio to determine compliance with the site's NPDES construction site storm water discharge permit. David Rapp was present at the site during the inspection.

Based on my observations, there were no obvious violations of the project's storm water discharge permit. I did not review the sediment control inspections logs or the site's storm water pollution prevention plan before my inspection. Inspection records of the erosion control BMPs are required to be kept on the construction site.

All erosion controls seem to be working efficiently at this point. I would like to compliment Mr. Rapp's crew on their effort of minimally disturbing the area surrounding the bridge over the Stillwater River.

As a reminder, please note that when construction is complete, and all areas of the site have been permanently stabilized with vegetation or other ground cover, the construction permit must be terminated. A one page "Notice of Termination" (NOT) form found at [http://www.epa.ohio.gov/Portals/35/permits/General\\_NOT.pdf](http://www.epa.ohio.gov/Portals/35/permits/General_NOT.pdf) must be completed and sent to the following address:

Ohio Environmental Protection Agency  
General Permit Program  
P.O. Box 1049  
Columbus, OH 43216-1049

Miami County Commissioners  
MIA-CR86-2.36 – Compliance Inspection Findings  
July 9, 2013  
Page 2

If you have any questions regarding the NPDES permit, you may contact me at (937) 204-1002 or via email [james.schwieterman@epa.ohio.gov](mailto:james.schwieterman@epa.ohio.gov).

Sincerely,

A handwritten signature in black ink, appearing to read "James Schwieterman", with a long horizontal flourish extending to the right.

James Schwieterman  
Storm Water Group  
Division of Surface Water

JS/tb

cc: Britt Havenar

Enclosed: Inspection Sheet

Ohio EPA DSW Storm Water Section, Construction Site Visit Information Form

Inspector initials: JS Visit date: 7/3/13 Permit # 16C04224-AG

Site Name: MIA-CR86-230 (PID 83349)

Site Address: Bradford-Bloomer Road over Stillwater River

People Contacted On Site: David Rapp

Phone: 937-423-4072 E-mail: \_\_\_\_\_

1. Did you see the following on site?

ITEM	YES	NO	Not Requested	Comments
NOI			✓	• David Rapp was working
Coverage Letter			✓	
SWP3			✓	
Inspection Records			✓	
Contractor & Subs signature document			✓	

2. Acreage Disturbed: 4.90

3. Site Status: Clearing/grubbing Rough Grading Storm sewers in \_\_\_\_\_  
 Streets in \_\_\_\_\_ Utilities installed \_\_\_\_\_ Final Grade \_\_\_\_\_ Final stabilization \_\_\_\_\_

4. Are BMPs needed: Yes

5. Are BMPs effective? All Some None No BMPs

Explain: Stone Wall / Rip Rap on disturbed creek bed with silt fence behind it.

6. What post construction controls are shown on the SWP3? N/A

7. Were Photos taken & saved? Yes 8. Was an NOV issued? No

Additional notes/comments:  
 • Minimal disturbance around creek bed where the new bridge bases will be placed.