



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Hall, Director

July 3, 2013

Tucker Bohm
The Daimler Group
1533 Lake Shore Drive
Columbus, Ohio 43204

**Re: Storm Water Inspection at Perimeter Retail Development/ Franklin County
Permit #: 4GC04080*AG**

Dear Mr. Bohm:

This letter is written in follow up to a construction storm water inspection by Jerome Hoke and Samuel Marotta of the Ohio EPA, at Perimeter Retail Development located at 6566 Perimeter Drive on June 18, 2013. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

Sediment and Erosion Controls:

- Failed silt fence was noted on the southeast and southwest corners, and the northern side of the site. Corrective measures must be implemented within three days from receipt of this letter (See Figure 1).

21 Day Rule:

- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Perimeter Retail Development 6-18-13



Figure 1: Silt fence in several locales around the site required maintenance.

Figure 1: Silt fence in several locales around the site required maintenance.